

Chevrolet_K Silverado - 4WD DTC Report



Company: --

Mailbox: --

Telephone: --

Website: --

Address: --

► Basic Information

VIN: 1GCEK14V45Z314829

Mileage: 0mile

Plate No.: MAPOV Lot 235

Report Date: 2025-08-01 02:13:01

SN: D7-WE56KE8

Version: V5.7.32_11.38

Path: GM->V14.50->Automatic Detection->2005->LD trk, MPV, incomplete->Chevrolet->K Silverado - 4WD

► System Scan Result

11 systems detected: 4 systems related to fault codes, 6 fault codes

NO.	System Name	Status
1	Powertrain(PS)	⚠ 3
2	Supplemental inflatable restraint(SIR)	⚠ 1
3	Radio(RADIO)	⚠ 1
4	Passenger presence system(PPS)	⚠ 1
5	ABS	✓
6	Heating and air conditioning(HAC)	✓
7	Body Control Module(BCM)	(!) ✓
8	Instrument panel cluster(IPC)	✓
9	VSES (if equipped)(VSES_IE)	✓
10	Traction assist (if equipped)(TA_IE)	✓
11	Generator battery control module(GBCM)	✓

► Trouble Code

■ Powertrain(PS) (DTC Amount: 3)

NO.	DTC Code	Trouble Code Descriptions	Status
1	P0059-BF	HO2S heater resistance bank 2 sensor 1	Last test:Failed This ignition:Not ran Since Cleared:Failed

2	P0154-29	HO2S circuit insufficient activity bank 2 sensor 1	Last test:Not ran This ignition:Not ran Since Cleared:Passed & failed
3	P0300-29	Engine misfire detected	Last test:Not ran This ignition:Not ran Since Cleared:Passed & failed

Supplemental inflatable restraint(SIR) (DTC Amount: 1)

NO.	DTC Code	Trouble Code Descriptions	Status
1	B0100-13	Electronic front end sensor 1 performance	

Radio(RADIO) (DTC Amount: 1)

NO.	DTC Code	Trouble Code Descriptions	Status
1	B1035-13	Audio output 2 right front circuit	

Passenger presence system(PPS) (DTC Amount: 1)

NO.	DTC Code	Trouble Code Descriptions	Status
1	B0100-13	Electronic front end sensor 1 performance	Last test:Failed This ignition:Passed Since Cleared:Passed

*This report is only responsible for the results of this detection