

Chevrolet_Tahoe DTC Report



Company: --

Mailbox: --

Telephone: --

Website: --

Address: --

► Basic Information

VIN: 1GNSK2E09ER184565

Mileage: 0mile

Plate No.: MAPOV Lot 257

Report Date: 2025-08-01 02:41:10

SN: D7-WE56KE8

Version: V5.7.32_11.38

Path: GM->V14.50->Automatic Detection->2014->Chevrolet->Tahoe

► System Scan Result

30 systems detected: 4 systems related to fault codes, 7 fault codes

NO.	System Name	Status
1	Body Control Module(BCM)	  3
2	Passenger Presence Module(PPM)	 2
3	Remote Control Door Lock Receiver(RCDLR)	  1
4	Rear Seat Heating Control Module(RSHCM)	 1
5	Engine Control Module(ECM)	
6	Transmission Control Module(TCM)	
7	Electronic Brake Control Module(EBCM)	
8	Inflatable Restraint Sensing and Diagnostic Module(IRSDM)	
9	Theft Deterrent Module(TDM)	
10	Instrument Cluster(IC)	
11	HVAC Control Module(HVACCM)	
12	Transfer Case Control Module(TCCM)	 
13	Chassis Control Module(CCM)	
14	Radio(RADIO)	
15	Passenger Door Switch Panel Control Module(PDSPCM)	
16	Driver Door Switch Panel Control Module(DDSPCM)	

17	Telematics Communication Interface Control Module	✓
18	Digital Radio Receiver Control Module	✓
19	Auxiliary Body Control Module	✓
20	Left Side Object Detection Control Module	✓
21	Parking Assist Control Module	✓
22	Right Side Object Detection Control Module	✓
23	Seat Memory Control Module	✓
24	Personal Audio Link Control Module	✓
25	Amplifier	✓
26	Rear Audio Control Module	✓
27	Liftgate Control Module	✓
28	Suspension Control Module	✓
29	Assist Step Control Module	✓
30	Parking Brake Control Module	✓

► Trouble Code

Body Control Module(BCM) (DTC Amount: 3)

NO.	DTC Code	Trouble Code Descriptions	Status
1	B1440-00	Power Mode Master Input Circuits Correlation	History
2	B2645-07	Ambient Light Sensor Circuit - High Voltage	History
3	U0200-00	Lost Communication with Passenger Door(s) Control Module	History

Remote Control Door Lock Receiver(RCDLR) (DTC Amount: 1)

NO.	DTC Code	Trouble Code Descriptions	Status
1	C0760-00	Left Rear Tire Pressure Sensor	History

Passenger Presence Module(PPM) (DTC Amount: 2)

NO.	DTC Code	Trouble Code Descriptions	Status
1	B0081-5A	Passenger Presence Module - Not Plausible	History
2	B1325-03	Control Module Power Circuit - Low Voltage	History

■ Rear Seat Heating Control Module(RSHCM) (DTC Amount: 1)

NO.	DTC Code	Trouble Code Descriptions	Status
1	C0760-00	Left Rear Tire Pressure Sensor	History

*This report is only responsible for the results of this detection