

Ford_Explorer DTC Report



Company: --

Telephone: --

Address: --

Mailbox: --

Website: --

Basic Information

VIN: 1FM5K8AR8JGB68968

Mileage: 0mile

Plate No.: MAPOV Lot 329

Report Date: 2025-08-01 03:28:45

SN: D7-WE56KE8

Version: V5.7.32_11.38

Path: Automatic Detection -> Vehicle:Explorer -> Model Year:2018 Year -> Vehicle displacement:3.7L -> Type Of Engine:TIVCT

System Scan Result

5 systems detected: 2 systems related to fault codes, 7 fault codes

NO.	System Name	Status
1	Body Control Module	⚠ 5
2	Powertrain Control Module	⚠ 2
3	Accessory Protocol Interface Module	✓
4	Battery Energy Control Module B	 ✓
5	Parking Aid Module	ADAS 

Trouble Code

Powertrain Control Module (DTC Amount: 2)

NO.	DTC Code	Trouble Code Descriptions	Status
1	P0138:00-68	O2 Sensor Circuit High Voltage (Bank 1 Sensor 2)	CMDTCs(Storage Trouble Code)
2	P0420:00-E8	Catalyst System Efficiency Below Threshold (Bank 1)	CMDTCs(Storage Trouble Code)

Body Control Module (DTC Amount: 5)

NO.	DTC Code	Trouble Code Descriptions	Status
1	U3006:16-08	Control Module Input Power A Circuit Open	CMDTCs(Storage Trouble Code)
2	U3007:16-08	Control Module Input Power B Circuit Open	CMDTCs(Storage Trouble Code)
3	U3013:16-08	Control Module Input Power C Circuit Open	CMDTCs(Storage Trouble Code)
4	U3014:16-08	Control Module Input Power D Circuit Open	CMDTCs(Storage Trouble Code)

5	B1438:03-08	Battery Current Sensor	CMDTCs(Storage Trouble Code)
---	-------------	------------------------	------------------------------

*This report is only responsible for the results of this detection